




Sometimes, the wires of channels are inverted.
So you must invert the numbers of lobes in the software



19

29/01/2012

Ech = 1:X



Sachs Roadster 800 / Ignitech TCI P4 V80

Ignitech TCI-P4 settings with Clouseau sytage 1 carbs

