





The precision of IAPS is not always perfect



1009.00 hPa = 101kPa



Sometimes all is OK with the default values.



But, Sometimes, you must increase or decrease the default value to read the real pressure (after programming!).

27A

12/07/2019

Ech = 1 : x



Sachs Roadster 800 / Suzuki VS 800GL Intruder / Suzuki VX 800 USA CA

IgniTech TCIP4 V88 V96 with IAP sensor 120kPa.
Adjustment of sensor values

